

BTW6.5.1.6000



BTW6.5.1.6000

Release Notes

November 18, 2014

Confidential and Proprietary Information

© Broadcom Corp., 2008, All rights reserved.
Printed in United States of America.
16340 West Bernardo Drive
San Diego, CA 92127
Phone: (858) 385-8800
Fax: (858) 385-8810

LICENSED SOFTWARE

©200x Broadcom Corporation

This program is the proprietary software of Broadcom Corporation and/or its licensors, and may only be used, duplicated, modified or distributed pursuant to the terms and conditions of a separate, written license agreement executed between you and Broadcom (an "Authorized License"). Except as set forth in an Authorized License, Broadcom grants no license (express or implied), right to use, or waiver of any kind with respect to the Software, and Broadcom expressly reserves all rights in and to the Software and all intellectual property rights therein. IF YOU HAVE NO AUTHORIZED LICENSE, THEN YOU HAVE NO RIGHT TO USE THIS SOFTWARE IN ANY WAY, AND SHOULD IMMEDIATELY NOTIFY BROADCOM AND DISCONTINUE ALL USE OF THE SOFTWARE.

Except as expressly set forth in the Authorized License,

1. This program, including its structure, sequence and organization, constitutes the valuable trade secrets of Broadcom, and you shall use all reasonable efforts to protect the confidentiality thereof, and to use this information only in connection with your use of Broadcom integrated circuit products.
2. TO THE MAXIMUM EXTENT PERMITTED BY LAW, THE SOFTWARE IS PROVIDED "AS IS" AND WITH ALL FAULTS AND BROADCOM MAKES NO PROMISES, REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS, IMPLIED, STATUTORY, OR OTHERWISE, WITH RESPECT TO THE SOFTWARE. BROADCOM SPECIFICALLY DISCLAIMS ANY AND ALL IMPLIED WARRANTIES OF TITLE, MERCHANTABILITY, NONINFRINGEMENT, FITNESS FOR A PARTICULAR PURPOSE, LACK OF VIRUSES, ACCURACY OR COMPLETENESS, QUIET ENJOYMENT, QUIET POSSESSION OR CORRESPONDENCE TO DESCRIPTION. YOU ASSUME THE ENTIRE RISK ARISING OUT OF USE OR PERFORMANCE OF THE SOFTWARE.
3. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL BROADCOM OR ITS LICENSORS BE LIABLE FOR (i) CONSEQUENTIAL, INCIDENTAL, SPECIAL, INDIRECT, OR EXEMPLARY DAMAGES WHATSOEVER ARISING OUT OF OR IN ANY WAY RELATING TO YOUR USE OF OR INABILITY TO USE THE SOFTWARE EVEN IF BROADCOM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES; OR (ii) ANY AMOUNT IN EXCESS OF THE AMOUNT ACTUALLY PAID FOR THE SOFTWARE ITSELF OR U.S. \$1, WHICHEVER IS GREATER. THESE LIMITATIONS SHALL APPLY NOTWITHSTANDING ANY FAILURE OF ESSENTIAL PURPOSE OF ANY LIMITED REMEDY.

BTW6.5.1.6000

INTRODUCTION

This is the release of BTW 6.5.1.6000 for the Windows 7 platform.

CUSTOMER SUPPORT PORTAL (CSP)

Customers can submit enhancements, changes and/or defects against releases of software or firmware via the Broadcom Customer Support Portal (CSP). CSP cases are replicated into the Broadcom Bluetooth engineering change management database for review by the engineering community and change control boards.

If your project or program is not listed inside the CSP please contact your Broadcom representative whom can configure the CSP system for use with your unique needs.

To start using the CSP please visit <http://support.broadcom.com>.

BTW6.5.1.6000

Driver Signing Report

Folder: BTW 6.5.1.6000_xxxx/Win32/

Driver:	Signed?	Signature:	Valid?	SubmissionID:	Version:	OS list	
bcbtums-win7x86-brcm.cat	Yes	WHQL	Yes	1692613	6.5.1.6000	Win7	
--> bcbtums.sys					12.0.0.6271		
bcbtumsld.cat	Yes	WHQL	Yes	1609541	6.5.1.4800	Win7	
--> bcbtums.sys					6.5.1.6271		
bcmhidnosr.cat	Yes	WHQL	Yes	1572233	1.0.0.101	Win7	Win8
btwampfl_svc.cat	Yes	WHQL	Yes	1691762	6.5.1.5900	Win7	
--> btwampfl.sys					6.5.1.5900		
btwaudio.cat	Yes	WHQL	Yes	1495656	6.5.1.2900	Win7	
--> btwavdt.sys					6.5.1.2500		
--> btwaudio.sys					6.5.1.2900		
btwavdt.cat	Yes	WHQL	Yes	1488214	6.5.1.2500	Vista	Win7
--> btwavdt.sys					6.5.1.2500		
btwdpan.cat	Yes	WHQL	Yes	1482014	6.5.1.300	Vista	Win7
--> btwdpan.sys					6.5.1.300		
btwl2cap.cat	Yes	WHQL	Yes	1479301	6.5.1.100	Vista	Win7
--> btwl2cap.sys					6.5.1.100		
btwrchid.cat	Yes	WHQL	Yes	1488202	6.5.1.2500	Vista	Win7
--> btwrchid.sys					6.5.1.2500		
--> btwavdt.sys					6.5.1.2500		

Folder: BTW 6.5.1.6000_xxxx/Win64/

Driver:	Signed?	Signature:	Valid?	SubmissionID:	Version:	OS list	
bcbtums-win7x64-brcm.cat	Yes	WHQL	Yes	1692613	6.5.1.6000	Win7	
--> bcbtums.sys					12.0.0.6271		
bcbtumsld.cat	Yes	WHQL	Yes	1609541	6.5.1.4800	Win7	
--> bcbtums.sys					6.5.1.6271		
bcmhidnosr.cat	Yes	WHQL	Yes	1572233	1.0.0.101	Win7	Win8
btwampfl_svc64.cat	Yes	WHQL	Yes	1691762	6.5.1.5900	Win7	
--> btwampfl.sys					6.5.1.5900		
btwaudio64.cat	Yes	WHQL	Yes	1495656	6.5.1.2900	Win7	
--> btwavdt.sys					6.5.1.2500		
--> btwaudio.sys					6.5.1.2900		
btwavdt64.cat	Yes	WHQL	Yes	1488214	6.5.1.2500	Vista	Win7
--> btwavdt.sys					6.5.1.2500		
btwdpan.cat	Yes	WHQL	Yes	1482014	6.5.1.300	Vista	Win7
--> btwdpan.sys					6.5.1.300		
btwl2cap64.cat	Yes	WHQL	Yes	1479301	6.5.1.100	Vista	Win7
--> btwl2cap.sys					6.5.1.100		
btwrchid64.cat	Yes	WHQL	Yes	1488202	6.5.1.2500	Vista	Win7
--> btwrchid.sys					6.5.1.2500		
--> btwavdt.sys					6.5.1.2500		

BTW6.5.1.6000

Resolved Defects [Build 6.5.1.6000]

BLTH03438680

Subsystem: Build

Headline:

Build did not produce new driver installer executable on
Release folder

BLTH03436591

Subsystem: Driver

Headline:

Need VID/PID to be added in BTW6 bcbtums WHCK driver for
43162 NGFF combo module

BLTH03435452

Subsystem:Driver

Headline:

Change FW for 4360+20702 HMB - VID/PID = 0B05/180A -
WHCK

BLTH03431113

Subsystem: Build

Headline:

Need new VID/PID to be added in BTW6.5 for
BCM4356A2 - Win7 WHCK